
Contents

Most recent information	1
Maintenance items	1
For Windows Driver	1
For Mac OS X Driver	1

Most recent information

We request that you always use the latest driver version for this unit. For information about the latest driver, check the TEAC Global Site (<http://teac-global.com/>).

Maintenance items

For Windows Driver

- After the Windows 8.1 update (KB 2919355) was installed, if a 24-bit option was selected for “Select the sample rate and bit depth to be used when running in shared mode” while a TASCAM USB audio interface was connected, the computer would restart when a Windows system sound played. This is been fixed.

Support models

Model name	latest driver version	latest firmware version
US-200	1.02 (update)	1.01 (no new update)
US-600	1.02 (update)	1.00 (no new update)
US-1641	2.05 (update)	1.02 (no new update)
US-1800	2.05 (update)	1.00 (no new update)
US-2000	2.05 (update)	1.01 (no new update)

For Mac OS X Driver

- Support has been added for OS X Yosemite (10.10).
- Support has been added for OS X Mavericks (10.9).

Support models

Model name	latest driver version	latest firmware version
US-200	3.00d8 *(no new update)	1.01 (no new update)
US-600		1.00 (no new update)
US-1800		1.00 (no new update)
US-2000		1.01 (no new update)

*For details, see “V3.00d8 (beta) Driver Release Notes for OS X Mavericks (v10.9)”.