
Most recent information

We request that you always use the latest driver version for this unit. For information about the latest driver, check the TEAC Global Site (<http://teac-global.com/>).

Maintenance items

For Windows Driver

- After the Windows 8.1 update (KB 2919355) was installed, if a 24-bit option was selected for “Select the sample rate and bit depth to be used when running in shared mode” while a TASCAM USB audio interface was connected, the computer would restart when a Windows system sound played. This is been fixed.

Support models

Model name	latest driver version			latest firmware version
	Windows Vista	Windows 7	Windows 8.1	
US-200	1.01	1.02		1.01
US-600	1.00	1.02		1.00
US-1641	2.02	2.05		1.02
US-1800	2.02	2.05		1.00
US-2000	2.02	2.05		1.01

For Mac OS X Driver

- Support has been added for OS X Yosemite (10.10).
- Support has been added for OS X Mavericks (10.9).

Support models

Model name	latest driver version					latest firmware version
	Mac OS X Snow Leopard (10.6)	OS X Lion (10.7)	OS X Mountain Lion (10.8)	OS X Mavericks (10.9)	OS X Yosemite (10.10)	
US-200	1.00		1.10	3.00* (update)		1.01
US-600	1.00		1.10	3.00* (update)		1.00
US-1641	2.00		2.10	3.00* (update)		1.02
US-1800	2.00		2.10	3.00* (update)		1.00
US-2000	2.01		2.10	3.00* (update)		1.01

* This version officially supports OS X Mavericks (10.9) and OS X Yosemite (10.10). For details, see “V3.00d8 (beta) driver Release Notes – for OS X Mavericks (10.9),” which has applicable contents.