



TECHNICAL INFORMATION

TASCAM DM-3200 V1.70 Firmware Update

No. 1007

DATE 19th March 2010

The firmware V1.70 for DM-3200 has been released with some new features, improvements, and bug fixes from V1.62

New features:

1. It supports IF-AV/DM (Aviom Pro16 A-Net Interface).
2. It supports IF-CB/DM (Cobra Net Interface Card).

Improvements and Bug fixes:

1. Digital Signal was not come out from Digital Output if the Fs Converter was set to On and Digital Input signal was not come to Digital Input. – fixed-
2. Studio Out signal did mute momentarily when SOLO was changed. – fixed –
3. When the RS-422 command (Sony P2 control) was sent, unexpected function might happen on the target machine. – fixed -
E.g. Pressing REC key during recording on target machine made Punch Out (Record off). It should keep Recording.

How to Firmware Update:

Refer to DM-3200 Service Manual “4. Firmware Update” page 20.

Visit the [ROM Data Library](#) in the TASCAM Service HP website to download Firmware