



# TECHNICAL INFORMATION

No. 1008

## TASCAM DM-4800 V1.70 Firmware Update

DATE 19th March 2010

The firmware V1.70 for DM-4800 has been released with some new features, improvements, and bug fixes from V1.62

### **New features:**

1. It supports IF-AV/DM (Aviom Pro16 A-Net Interface).
2. It supports IF-CB/DM (Cobra Net Interface Card).

### **Improvements and Bug fixes:**

1. Digital Signal was not come out from Digital Output if the Fs Converter was set to On and Digital Input signal was not come to Digital Input. – fixed-
2. Studio Out signal did mute momentarily when SOLO was changed. – fixed –
3. When the RS-422 command (Sony P2 control) was sent, unexpected function might happen on the target machine. – fixed -  
E.g. Pressing REC key during recording on target machine made Punch Out (Record off). It should keep Recording.
4. When IF-FW/DMmk2 was installed into Slot 3, Track9-32 in Slot 3 could not be selected as Output. – fixed -

### **How to Firmware Update:**

Refer to DM-4800 Service Manual “4. Firmware Update” page 20.

Visit the [ROM Data Library](#) in the TASCAM Service HP website to download Firmware.