

TASCAM

TEAC Professional Division
X-48

Read Me – Version 1.03
August 2, 2007

Thank you for your purchase of the TASCAM X-48 Digital Audio Workstation. Following are a few things that didn't make it into the Version 1.00 documentation.

- **Do not make changes to the X-48's BIOS. Doing so may cause your X-48 to not boot, requiring non-warranty factory service.**
- When installing the optional I/O cards, take care to ensure that the guide key on the flat gray cable goes into the notch on the connector(See Fig.1 below).
- If you need to use the provided System Restore CD, **you must disconnect any external drives first.** Using the System Restore CD will erase the data on any connected external drives.
- If you need to use the provided System Restore CD, **you must disconnect any USB copy protection devices first.**

Read Me – バージョン 1.03
2007 / 8 / 2

ご注意

- X-48 の BIOS の設定内容を変更しないで下さい。もし変更した場合、X-48 が起動しなくなる等、正常に動作しなくなる可能性があります。この場合、有償での修理となりますので、予めご了承下さい。
- 付属の Restore CD でシステムを再インストールする場合、必ず外付けデバイス（FireWire または USB に接続されている HDD ドライブやフラッシュメモリ等）を外した状態で再インストールを実行して下さい。Restore CD でのシステムの再インストールは、外付けデバイス内のデータを消去してしまいます。
- オプション I/O カードを装着時、基板側コネクタの凹部に、50 ピンフラットケーブル側コネクタの凸部が入る様に、十分に方向を確認してケーブルを装着して下さい（下図参照）。




Fig. 1