



NOTES ON HOTFIX:

During the testing phase of the US-428 we were able to determine, with the assistance of Microsoft, that a bug exists in Windows98 Second Edition. When powering off any USB device, Windows will freeze, necessitating a reboot.

Microsoft has supplied us with the Hotfix file supplied on the enclosed CD-ROM. If you are running Win98SE, we suggest you install the Hotfix.

Note that the US-428 disk contains two Hotfix files. The one with the "e" designation is the English version, and should be run in most cases. The one with the "j" designation is the Japanese version.

How to tell if you're running First or Second Edition:

1. Right-click on the My Computer icon on your desktop.
2. Highlight and click Properties.
3. Select the General tab. The dialog box should read:
System:
Microsoft Windows 98
Second Edition
x.xx.xxxxx <<(this will be the build number)