

## **TASCAM US-428 Driver Version 3.2.1**

### **Installation/Removal Procedures for Mac OS 9.2.2**

The file (US428\_OS9\_3\_21.hqx) is a self-extracting archive, which means that Stuffit will automatically expand the file once it finishes downloading it. Once unStuffed, an installer icon labeled 'US-428 v3.2.1 Installer' will appear in the same folder the .hqx file was downloaded into.

#### **To install the 3.2.1 driver software:**

1. Double-click on the 'US-428 v3.2.1 Installer' icon. You should now see the splash screen for the installer. Turn OFF your US-428 and click 'Continue' to advance to the next window.
2. 'Important Information' – this window provides a brief description of each file installed and offers the option to print if desired. Click 'Continue' to proceed.
3. 'Software License Agreement' – Please read and then click 'Agree' to proceed and verify that you agree with the Software License Agreement on the warning panel.
4. You will see the message 'preparing to install'. This might take as long as a minute or two if you have OSX installed on the same drive, as the installer must look through the whole disk for the correct locations to install the components.
5. 'Easy Install'. Acknowledge by either clicking 'Install' or pressing 'Return'. If you do not wish to continue you may click 'Quit' at this point'.
6. Press 'Yes' or Return to acknowledge that your computer might restart after installation.
7. After the software has been successfully installed, click 'Restart' to complete the process.