

IF-FW/DM Version 1.01 Release Notes

Included in your download

- For Windows
 - v1.01 Windows driver installer
 - v1.01 IF-FW/DM firmware (.bcd file)
 - This document
- For Mac
 - IF-FW/DM firmware updater for OSX
 - v1.01 IF-FW/DM firmware (.bcd file)
 - This document

Note that the IF-FW/DM firmware updater is built into the Windows control panel while it is a separate app for OSX.

Note that only Windows requires the v1.01 driver update since OSX includes its own drivers for the IF-FW/DM.

Maintenance Items

- Sync reliability between the IF-FW/DM and a host PC has been improved.
- A problem causing no audio return from the host computer on certain DM-24 mixers has been corrected.

Installation for PC:

Perform the steps below in the following order:

Updating the Windows Driver

- Update the IF-FW/DM Windows driver by running the v1.01 installer. It will prompt you then automatically uninstall the previous v1.00 version.

Updating the IF-FW/DM Firmware

1. Under the Tools menu of the IF-FW/DM control panel, select the menu item to Update Firmware on Card.
2. You will be prompted to locate the v1.01 .bcd file.

Installation for Mac:

Your Mac must meet the minimum system requirements for the IF-FW/DM to perform the following update. If it does not, your IF-FW/DM could experience an incomplete firmware update, requiring its replacement. Please refer to the IF-FW/DM Owner's Manual if you are unsure about the minimum system requirements.

1. Run the OSX IF-FW/DM Firmware Updater and follow the detailed on screen instructions
2. You will be prompted to locate the v1.01 .bcd file